

FO-POXY (COATING REMOVER)

DESCRIPTION :

Fo-Poxy (Coating Remover) is a low viscosity deep penetrating action coating remover which has ideally been formulated to remove most commonly used industrial paints viz. enamel, epoxy, alkyds, etc.

APPLICATION :

1. Wipe clean the area to be stripped of paints from all contaminants.
2. Apply **Fo-Poxy (Coating Remover)** by means of paint brush on the area to be stripped.
3. Leave to dry for some time.
4. Scrap the surface with chisel / scrapper / knife.
5. Repeat the above procedures till the coating is completely removed in flake form.
6. Once the paint is stripped off; thoroughly wash clean the stripped part with plenty of water.

PACKING : Available in 1 Litre and 5 Litres Containers.

NOTES :

- Wear protective Rubber gloves and masks when operating.
- The consumption would depend on the type of paint to be stripped and the layers of coating to be removed.

MANUFACTURED BY :

AQUADRA FORSPEC PVT. LTD., Mumbai, India

Tel: +91 9820 393 292 / +91 98209 90182

E-mail : aquadraforspec@gmail.com

The information contained and the recommendations made in this data sheet are based upon data collected and believed by us to be correct. However, no guarantee or warranty of any kind, expressed or implied, is made herein with respect to the merchandise described and we assume no responsibility for the results or the use thereof.